ARC

LIGHTCORP

Installation Instructions

Clamp Mount Variation

Included in Package:
- PDU Unit
- 2x Thumb Screws

How to Install:

1. Slide unit mount onto edge of surface. (Fig. 1)
2. Tighten thumb screws on underside of the surface. (Fig. 2)
3. Plug in the unit.

Under Surface Mount Variation

Included in Package:
- PDU Unit
- 4x #10 Wood Screws

Tools Needed:
- Phillips head screwdriver
- Pilot drill bit (optional)
- Drill
- Pencil

How to Install:

1. Locate where the unit will be mounted, marking hole locations with a pencil. (Fig. 3).
2. Remove unit and pre-drill pilot holes in marked locations.
3. Align unit with pilot holes and use a screwdriver to secure in place with provided screws (Fig. 4).




Fig. 1




Fig. 2




Fig. 3




Fig. 4

FCC Compliance

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. This Class A digital apparatus complies with CanCet appareil numériqué de la classe A est conformé à la norme NMB-003 du Canada.

Assemblies are not intended for industrial/commercial applications in Canada. (CSA 308 pg. 13 defines commercial/industrial as “factories, garages, construction sites”).

WARNING

No user serviceable parts. For use in dry locations. To reduce the risk of electric shock- use only indoors.

ATTENTION: Pour réduire le risque d’électrocution, utilisez uniquement à l’interiéur. Utiliser uniquement dans des endroits secs.